



Existing school roof condition: Facing south



Roof junction with rear of house.