



School interior to party wall with house. Note oil feed pipe running full length of school to oil tank in rear garden. (Oil tank to be drained and demolished.)



Only existing one of three original cast iron lozenge design front windows to front façade. Replacement required for original two missing windows to match existing for Grade 11 building.